

CAPITAL INVESTMENT COSTS FOR PLANT AND EQUIPMENT IN IRON AND STEELMAKING

Research Report

CONTENTS		Page
CONTENTS		1
LIST OF EXHIBITS		3
DISCLAIMER		7
EXECUTIVE SUMMARY		8
1.	INTRODUCTION	9
1.1	Background	9
1.2	Definitions	9
1.3	Scope of report	10
1.4	Abbreviations	11
1.5	Sources of information	12
2.	INVESTMENTS	13
2.1	Steel plants	13
2.1.1	BOF / cast slab	13
2.1.2	Integrated steel plant.....	14
2.1.3	EAF / cast billet	15
2.1.4	Scrap based steelworks	16
2.2	Upstream investments	17
2.2.1	Sinter plant	17
2.2.2	Coke batteries	18
2.2.3	Direct reduced iron plant	19
2.2.4	Blast furnace	20
2.2.5	Basic oxygen furnace	21
2.2.6	Electric arc furnace	22
2.2.7	Induction furnace	23
2.2.8	Slab casting	24
2.2.9	Billet and bloom casting	25
2.3	Downstream investments	26
2.3.1	Steel plate	26
2.3.2	Hot rolled coil	28
2.3.3	Cold rolled coil	29
2.3.4	Hot dip galvanising	30
2.3.5	Tin plate	31
2.3.6	Organic coating	32
2.3.7	Heavy sections and rail	33
2.3.8	Steel bar	35
2.3.9	Wire rod	37
2.3.10	Drawn wire	38
2.3.11	Welded tube	39
2.3.12	Seamless tube	40

CONTENTS		Page
2.4	Ancillary investments	41
2.4.1	Pellet plant	41
2.4.2	Coal washing plant	43
2.4.3	Lime plant	43
2.4.4	Pulverised coal injection	44
2.4.5	Hot metal desulphurisation	45
2.4.6	Blast furnace reline	46
2.4.7	Ladle furnace	46
2.4.8	Vacuum degassing	47
2.4.9	Air separation unit	48
2.4.10	Power plant	49
2.4.11	Temper / skin-pass rolling	50
2.4.12	Slitting line	51
2.4.13	Pickling line	52
2.4.14	Waste water treatment plant	53
2.4.15	Acid regeneration plant	53
3.	SOME INVESTMENT CHOICES	55
3.1	Steelmaking: BOF versus EAF and the induction furnace	55
3.2	Hot rolling of coil – the Steckel Mill	55
3.3	Cold rolling: tandem versus reversing	57
3.4	Zinc Coating: Hot dip- versus electro-galvanised	57
3.5	Tube: welded versus seamless	58
3.6	Temper mill versus skin-pass mill	58
4.	DISCUSSION	59
4.1	Investments	59
4.1.1	Investment summary	59
4.1.2	Investors	60
4.1.3	Locations.....	62
4.2	Cost components	63
4.3	Performance guarantees – India & China	65
4.4	Employment impact	67
4.5	The value added chain	69
4.6	Investment cost variability	70
4.6.1	The importance of output volume	70
4.6.2	Economies of scale	70
4.6.3	Other cost drivers	72
4.7	Investment trends	74
4.7.1	Product focus	75
4.7.2	Plant geography	75
4.7.3	Plant design	76
4.7.5	Adoption of new fuels and fuel types	77
5.	CAPEX COST vs CAPACITY CHARTS	79
6.	CONCLUSIONS	90